

WORKSITE PROTOCOLS

In the interest of your safety, we ask that the following rules be observed:

JDC require all persons on any worksite to:

- Sign in and out of Hammertech each working day
- Wear high visibility clothing
- Wear fully enclosed, flat soled, steel cap work boots
- Wear other PPE as signed (hardhat, gloves etc)
- Observe and adhere to all signage and barricading
- Only operate plant and equipment that they are approved and nominated to operate
- Not enter site if impaired by alcohol or drugs (BAC limit is 0.00% and drug levels are as per the AS)
- Notify the Site Supervisor immediately of any unsafe practices, incident or near miss

Special conditions for Visitors (non- working) Requirements on site to:

- Sign in and out of Hammertech as a guest.
- Must be accompanied by a person nominated by the Site Supervisor at all times
- Must not take photographs or videos without the permission of the Site Supervisor.
- Be respectful that the site is a workplace
- Give way to mobile plant at all times.
- not operate or use any plant or equipment unless specifically instructed to do so

In the event of an incident:

- First Aid kits are kept in site offices and in vehicles.
- The Site Supervisor is a trained First Aid Officer



In the event of an emergency:

- Follow the instructions of the Site Supervisor.
- Do not leave the site without permission from the Site Supervisor

It is a condition of entry that all persons entering shall, if called upon, submit to be searched and visitors are not permitted to remove any property from site without the express permission of any member of a JDC Director.

